

指示なき角部は糸面取りの事

外径研削代

内径研削代

端面研削代

35

- 5 -


12 - S

3

- S  0.8-S

號呼	A	個數
H16	16	
H17	17	
H18	18	
H19	19	
H20	20	
H21	21	
H22	22	
H23	23	.
H24	24	
H25	25	
H26	26	
H27	27	
H28	28	
H29	29	

株呼	A	個数
H30	30	
H31	31	
H32	32	
H33	33	
H34	34	
H35	35	
H36	36	



本図は称呼 H16 ≤ A ≤ H36 時使用