

TAC Rockford runout arbors for lathe centers are manufactured using hardened gauge-quality steel, and include a certificate of accuracy. Shorter arbors have a cylindricity ≤ 0.002 mm; longer lengths ≤ 0.003 mm.

Cases are not included. Contact us for high quality gauge crib and travel case options.


Contact us for special sizes or configurations. Hard chrome versions available on request.

Description	Length (mm)	Diameter (mm)	Part Number
Runout Arbor for Centers	300	32	490.520.032.300
Runout Arbor for Centers	400	35	490.520.035.400
Runout Arbor for Centers	250	40	490.520.040.250
Runout Arbor for Centers	500	40	490.520.040.500
Runout Arbor for Centers	600	50	490.520.050.600
Runout Arbor for Centers	500	63	490.520.063.500
Runout Arbor for Centers	700	70	490.520.070.700
Runout Arbor for Centers	1000	80	490.520.080.01K
Runout Arbor for Centers	750	80	490.520.080.750
Runout Arbor for Centers	1000	90	490.520.090.01K
Runout Arbor for Centers	800	90	490.520.090.800

Preventive Maintenance Gauges

Dimensional Gauges, Balancing Masters, Coolant Supply Gauges, Center Height/Master Setting, Tool Changer Alignment Gauges, Machine Set-up Gauges. Also ask us about custom gauges and personalized solutions for your machine or machine tool.

Runout Test Arbors



Available for all major machine tapers, including CAT/DIN/BT Steep Taper, HSK, Capto, KM, Morse, and others.

Chuck Force Gauges



Measure chuck jaw clamping force at high speeds. Also available for other chuck measuring applications.

Drawbar Force Gauges



Measure tool clamping force to protect spindles and ensure machining accuracy.

Custom Machine Tool Gauges

Any gauge for any machine or machine tool.

